



Publication No. WI-2014-13

8 December 2014

## **The Watershed Institute**

Division of Science and  
Environmental Policy  
California State University Monterey Bay  
<http://watershed.csumb.edu>

100 Campus Center, Seaside, CA, 93955-8001  
831 582 4452 / 4431

*Central  
Coast  
Watershed  
Studies*

**CCoWS**

## **Potrero Creek Restoration Santa Lucia Preserve Monterey County (CA): Year Five Monitoring**

Doug Smith PhD  
Dana Riggs, Principal, WRA, Inc.

Lead author contact details:  
[dosmith@csumb.edu](mailto:dosmith@csumb.edu)

## Acknowledgements

We are grateful for the assistance of:

- Field assistance by Amelia Olson, Joelle Demetre, Dan Muratore, and Scott Odermatt

This report may be cited as:

Smith DP and Riggs D. (2014) Potrero Creek Restoration, Santa Lucia Preserve, Monterey County (CA): Year Five Monitoring: The Watershed Institute, California State Monterey Bay, Publication No. WI-2014-13, 43pp.

Submitted to:

Forrest W. Arthur, General Manager  
Santa Lucia Community Service District  
One Rancho San Carlos Road  
Carmel, CA, 93923

## **Executive Summary**

A 50 m long reach of Potrero Creek was realigned in 2009 to prevent undermining of Chamisal Pass Road. In keeping with permit requirements, this report details geomorphic and ecological monitoring in 2014--the fifth year after realignment. The Year-5 success criteria and standards include the following parameters.

- Water quality of the restored reach will be equal to or better than that of the reference reach, and better than pre-existing conditions.
- Water quality of the downstream reach will exceed pre-existing conditions.
- Survival of plantings will exceed 80 percent.
- Plants rated as "high" or "moderate" invasive species in the California Invasive Plant Inventory (Cal-IPC 2010) will not exceed five percent cover within the riparian area.
- The pilot channel banks will be stabilized and not show signs of significant erosion.
- The restored reach will have a habitat assessment value at least fifty percent greater than the pre-existing value, and all parameters should at least meet suboptimal conditions based on the CDFG California Stream Bio-assessment Procedure.

All parameters meet Year-5 success criteria, with the exception of the habitat assessment value. Environmental factors likely play a role in habitat assessment values such that a 50 percent increase may not be obtainable. Channel erosion should be visually monitored following high flow events. Bank stabilization will increase as riparian roots continue to grow.

### ***Geomorphic Monitoring***

The longitudinal profile and reference reaches above and below the pilot channel show channel evolution in keeping with a watershed that has a high rate of bedload input. Two cross sections located at the upper and lower end of the pilot channel exhibit minor adjustments that are within expected values.

A cross section located in the middle of the pilot channel reach indicated that the right bank (downstream view) eroded between 2009 and 2012 in response to bar deposition on the left bank. Surveys in 2014 indicate that the erosion has not continued, but there were no high flow events between 2012 and 2014. Channel widening was anticipated in the design phase of the project because only a narrow pilot channel was excavated. It is unclear how much more widening to anticipate.

### ***Riparian Mitigation Monitoring***

Upland vegetation is recovering well, as demonstrated by a high absolute cover of native species, and little bare ground, no observed invasive plants. No additional upland planting is recommended at this time.

In-stream and bankside vegetation met the 80 percent cover criteria in Year 5 and the banks of the pilot channel appeared relatively stable compared with previous years. Root structures and large boulders provide additional structural complexity where in-stream plants such as *Carex spp.* and *scirpus*, have failed to take hold. Overall, measures implemented in year 3 including trimming and the addition of dogwood poles have increased overall in-stream cover when compared with the reference reach. Based on the meeting of performance criteria, no additional measures are recommended.

#### ***Wildlife Biological Monitoring***

On a qualitative level, the pilot channel provides better habitat than what was previously present in the oxbow. While the overall habitat assessment value from Year 5 does not meet the performance criteria outlined in the *Potrero Creek Restoration Monitoring and Management Plan*, as required by the Project's RWQCB, CDFG, and Corps, the habitat is measurably better than baseline conditions. A 10 percent increase in value overall from baseline conditions was measured in Year 5 and nearly all values were at least suboptimal or increasing in value. No decreases in values were measured except where such decreases were evident throughout the reach and likely the result of environmental factors rather than project-related. As such, no further wildlife monitoring is recommended.

## Table of Contents

Acknowledgements .....	ii
Executive Summary.....	iii
Table of Contents .....	5
1 Introduction .....	6
1.1 Background .....	6
1.2 Study area .....	7
1.3 Goal .....	9
2 Methods.....	10
2.1 Geomorphology .....	10
2.2 Riparian Vegetation Monitoring.....	11
2.3 Wildlife Monitoring.....	11
3 Results .....	12
3.1 Geomorphology .....	12
3.2 Riparian Vegetation .....	22
3.3 Wildlife .....	23
4 Recommendations .....	27
4.1 Geomorphology .....	27
4.2 Riparian Vegetation .....	28
4.3 Wildlife .....	28
5 References .....	28
6 Appendix A: Photomonitoring.....	30
7 Appendix B: Physical Habitat Quality Assessment Field Notes.....	37


# **1 Introduction**

## **1.1 Background**

The following background paragraphs are derived from WRA (2010). In 2009, a short reach of Potrero Creek (Fig. 1) was realigned to prevent bank erosion that threatened both Chamisal Pass Road and local aquatic environmental quality. Erosion of the right bank (downstream view) was undermining a tall denuded bank that supports Chamisal Pass Road. If left unchecked, the erosion would have resulted in reactivation of a large landslide and major construction work to rebuild the road. Further, the erosion from the bank would have chronically contributed excess fine sediment to Potrero Creek (potentially occluding the channel), thereby decreasing aquatic and riparian habitat value. To repair this condition, the eroding stream reach was blocked at the upstream end, and a new pilot channel was constructed to bypass the erosion site.

The “restored” reach of Potrero Creek was designed to function as a natural stream reach with geomorphic integrity and an intact riparian corridor. This restoration project was permitted under the condition that it be monitored for geomorphic and ecological quality for a minimum of five years. The specific requirements are detailed by the U.S. Army Corps of Engineers (ACOE) Section 404 permit File Number 2008-003026, California Department of Fish and Game (CDFG) Stream Alteration Agreement No. 2008-008-R4, and Regional Water Quality Control Board (RWQCB) Water Quality Certification #32708WQ06, and as specified in the Potrero Creek Restoration Plan (WRA 2009).

Details of the project design and construction can be found in several antecedent reports (WRA 2009, 2010, 2012) on file with the Santa Lucia Conservancy, ACOE, RWQCB and CDFG.



**Figure 1: Box shows location of Potrero Creek restoration in the Carmel Watershed.**

## 1.2 Study area

Potrero Creek is located in the Carmel River watershed adjacent to Chamisal Pass Road on Santa Lucia Preserve property at approximately 602410 E 4041150 N (UTM zone 10 meters) (Fig. 2). The surface geology is landslide material that is clearly visible in a road cut above the restoration site. Below the landslide is Tertiary marine shale of the Monterey Formation (Fig. 2). The Monterey formation and derivative soils are prone to landslide hazard (Fig. 2) and erosion (Fig. 3).






Figure 2: Location and geology of restoration site. GIS data from Rosenberg (2001)




Figure3: Erosion potential of substrate of Potrero watershed. GIS data from Rosenberg (2001)



### 1.3 Goal

The goal of this work is to assess the physical and biological conditions of the restoration site in the fifth year following construction. The following criteria and standards guided the monitoring methods used this year. The criteria and standards below are copied from WRA (2010).

---

#### YEAR 1

- Water quality will resemble that of the upstream and downstream reach.
- Survival of plantings will exceed 90 percent.<sup>1</sup>
- Plants rated as “high” or “moderate” invasive species in the California Invasive Plant Inventory (Cal-IPC 2010) will not exceed five percent cover within the riparian area<sup>2</sup>.
- The pilot channel banks will be stabilized by native vegetation and not show signs of significant erosion.
- The restored reach will have a habitat assessment value greater than the preexisting reach based on the CDFG California Stream Bio-assessment Procedure.

<sup>1</sup> The *Restoration Plan* sets survival targets only for “planted riparian trees”. However, the CDFG *Stream Alteration Agreement* specifies a Year 5 performance criterion of 80% survival for all plantings, so the monitoring program will assess all plantings during each monitoring effort.

<sup>2</sup> The *Restoration Plan* refers instead to the California Exotic Pest Plant Council (CalEPPC) “A” List or Red Alert List, an older ranking system and organization name replaced by the Cal-IPC Inventory. WRA has converted this performance criterion to “moderate” and “high” invasives, as those species would most threaten the success of the Project’s revegetation efforts.

#### YEAR 3

- Water quality of the restored reach will be equal to or better than that of the reference reach.
- Survival of planted riparian trees will exceed 85 percent.
- Plants rated as “high” or “moderate” invasive species in the California Invasive Plant Inventory (Cal-IPC 2010) will not exceed five percent cover within the riparian area.
- The pilot channel banks will be stabilized and not show signs of significant erosion.
- The restored reach will have a habitat assessment value greater than the preexisting value for Year 1, based on the CDFG California Stream Bioassessment Procedure.

#### YEAR 5

- Water quality of the restored reach will be equal to or better than that of the reference reach, and better than pre-existing conditions.
  - Water quality of the downstream reach will exceed pre-existing conditions.
  - Survival of plantings will exceed 80 percent.
  - Plants rated as “high” or “moderate” invasive species in the California Invasive Plant Inventory (Cal-IPC 2010) will not exceed five percent cover within the riparian area.
  - The pilot channel banks will be stabilized and not show signs of significant erosion.
  - The restored reach will have a habitat assessment value at least fifty percent greater than the pre-existing value, and all parameters should at least meet suboptimal conditions based on the CDFG California Stream Bioassessment Procedure.
-

## 2 Methods

The following methods were used to monitor the restoration site. We generally employed the same techniques used in previous work at this site to improve inter-annual comparison (WRA, 2010; Smith et al., 2012).

### 2.1 Geomorphology

Autolevel and stadia rod surveys captured changes in cross sectional geometry and longitudinal profile of the creek. The surveys were tied to benchmark elevations established in WRA (2010, 2012) and reoccupied by Smith et al. (2014), and are plotted atop previous surveys to analyze geomorphic change. These surveys are used to assess the magnitude of sediment aggradation or degradation in the channel and to assess bank stability. Cross sectional geometry and average channel gradients are also compared with previously obtained values. A spike in a large redwood tree located 70 ft upstream from the restoration site serves as a local elevation benchmark for the cross sections and profile. In keeping with previous surveys, the spike was assigned an arbitrary elevation of 100 ft.

The longitudinal profile began at the downstream edge of a large redwood tree that has fallen across the creek, approximately 15 ft up-valley of the redwood with the benchmark spike. The profile ended 14 ft downstream from cross section 5. Five cross sections were resurveyed using the head pins as in previous years.

The following notes describe the locations of five surveyed cross sections (WRA 2010).

- XSEC 1 located upstream of the restoration area,
- XSEC 2 located at the upstream end of the pilot channel,
- XSEC 3 located approximately in the center of the pilot channel,
- XSEC 4 located at the downstream end of the pilot channel,
- XSEC 5 located downstream of the restoration area.

XSEC 1 and 5 are outside the restored reach; they serve to monitor ambient conditions for comparison with XSEC 2, XSEC 3, and XSEC 4, which cross both the abandoned and new channels within the restoration reach. The cross section survey history is shown in Table 1.

Table 1: Geomorphic Survey History

Cross Section	Pre-construction	Post-construction (2009)	Year 1 (2010)	Year 3 (2012)	Year 5 (2014)
XSEC 1	●		●	●	●
XSEC 2	●	●	●	●	●
XSEC 3	●	●	●	●	●
XSEC 4	●	●	●	●	●
XSEC 5	●		●	●	●
Long Profile	●	●	●	●	●

Sediment deposition and erosion monitoring was also documented with monitoring photographs taken immediately prior to restoration (August 2009), immediately following restoration, during Year 1 monitoring (August 5, 2010), during Year 3 monitoring (September 26, 2012), and during year 5 monitoring (August 30, 2014). Monitoring photographs were taken at the cross sections and in other key locations to document geomorphic change. Monitoring photographs are provided in Appendix A.

## 2.2 Riparian Vegetation Monitoring

Year 1 riparian vegetation monitoring was conducted on August 5, 2010 by WRA botanist Jennifer Mathers. Year 3 monitoring was conducted on September 26 & 27, 2012 by Santa Lucia Conservancy plant ecologist Chris Hauser. In both years, monitoring consisted of a simple count of live and dead plantings throughout the restoration area, and cover of non-native plants was assessed in all disturbed areas resulting from project construction. Year 5 monitoring was conducted on October 22, 2014 by WRA biologist Dana Riggs. In 2014, monitoring consisted of estimating total percent cover of the restoration area of plantings and invasive plant species to determine if success criteria were met.

## 2.3 Wildlife Monitoring

General wildlife surveys performed included visual surveys for amphibians and fish during monitoring surveys. Biologists began each survey at the downstream end of the long profile, and slowly moved upstream along the banks. Observations included species present, if any special status species were observed, the general location of species, and what habitat features were utilized. Wildlife visual surveys were conducted prior to the geomorphic surveys if coinciding on the same date, to maximize the potential of detecting special status species, and were conducted throughout the length of the long profile.

Stream habitat assessments were also performed on each stream reach utilizing the CDFG California Stream Bio-assessment Procedure field data sheets for high and low gradient streams (Appendix B). The CDFG procedure uses a qualitative assessment of habitat parameters such as epifaunal substrate and available cover, embeddedness, velocity and depth regime, sediment deposition, channel flow status, channel alteration, frequency of riffles or bends, bank stability, vegetative protection, and riparian vegetative zone width. Additionally, water clarity, temperature, pH, and conductivity were measured. The maximum score for each reach is 200, with high scores indicating optimal habitat and low scores indicating poor habitat quality for species. Each reach was assessed and a total score was assigned and compared.

### **3 Results**

#### **3.1 Geomorphology**

Year 5 longitudinal profile and cross section surveys were conducted on August 30, 2014. All headpins and temporary benchmarks were located, reflagged and reoccupied during the survey, except for the left headpin of cross section 4. The left headpin is visible for cross section tape alignment, but a fallen tree trunk has covered the pin and 2 nearby survey shots on that transect. Inter-annual survey precision is acceptable based upon the good agreement between left and right head pin elevations in the cross sections plots.

A total of 278 feet of Potrero Creek thalweg were surveyed for the longitudinal profile; which is consistent with previous surveys. Figure 4 shows the longitudinal profile results for Year 5 monitoring overlaid with all previous surveys. Table 2 shows the overall gradient for each of the long profile surveys. The following changes are apparent in the profile.

- Overall gradient decrease is driven by net erosion at upstream end of the survey reach. The gradient within the restoration reach has remained relatively stable at about 2.2%.
- An upward deflection in the profile located at 150 ft in 2009 and 110 ft in 2010 is less apparent in 2012 and 2014.
- Overall variation in the profile cannot be differentiated from steady-state equilibrium over the short 5 year monitoring period.
- A qualitative review of the site in August 2011 noted that a log had made a short step and pool sequence near the exit of the restoration reach (WRA 2012). That log and step-pool geometry are still present in September 2012. The feature is located at approximately 223 ft in the profile (Fig. 4). The scour at the

downstream side of the log provides perennial pool habitat, still present in August 2014, following several relatively dry years.

### Long Profile for Potrero Creek, CA Restoration Area




Figure 4: Longitudinal profile of Potrero creek restoration site.

Table 2: Longitudinal Profile Gradient and Changes in Slope

Survey	Gradient (% slope)	Incremental Change in Gradient (% slope)
Pre-restoration	2.31	N/A
2009 Post-restoration	2.36	+0.05
2010 Year 1 Monitoring	2.26	-0.10
2012 Year 3 Monitoring	1.96	-0.30
2014 Year 5 Monitoring	1.87	-0.09
<b>Overall post-restoration change (2014–2009)</b>		<b>-0.49</b>

The five cross sectional profiles are presented in Figures 5 through 9. The resulting changes in cross sectional area are reported in Table 3.

The upstream reference profile (Fig. 5) and the upstream end of the restored reach (Fig. 6) show that the stream has been alternately aggrading and degrading, in keeping with

previous interpretations (WRA 2010, 2012; Smith et al., 2012). Alternating periods of aggradation and degradation show that the stream reach is passing an episodically-high upstream sediment load on a multiannual time frame without net change. While this behavior is in keeping with steady-state equilibrium, the time under evaluation is too short to draw that conclusion. Of note is that the amount of vertical change (2 ft to 3 ft) is very high for a small creek, indicating that there is likely stream-bank instability or other chronic sediment sources located higher in the watershed. Figure 2 indicates that this watershed is underlain by highly erodible substrate that will generate excess sediment when disturbed. There has been virtually no change in channel geometry since 2012 because there have been no geomorphically-significant flows during that period.

Cross section 3 (Fig. 7) is located in the middle of the pilot channel reach. Both visual inspection and the cross sectional survey indicated rapid erosion at this site between 2009 and 2012. WRA (2012) reported excess erosion here in the August 2011 visual inspection as well. Bank sloughing and sediment recruitment have constructed a side-attached bar that has grown from left to right across the original pilot channel thalweg (Fig. 7, Fig 10, Appendix A p. 32). The bar has forced scouring flows against the right bank. The right bank is undercut from 1 to 3 feet, and has retreated approximately 5 feet since the 2010 survey. At this cross section, the channel has generally enlarged in size since inception (Fig. 7; Table 3, Appendix A, p. 32). There has been virtually no change in channel geometry since 2012 because there have been no geomorphically-significant flows during that period.

Cross section 4, at the downstream end of the pilot channel, shows bank stability and net aggradation of 1.5 feet in the channel and 2 feet in the oxbow (Fig. 8). The downstream reference cross section (Fig. 9) has gradually built a side-attached bar on the right bank. In response, the thalweg has moved from right to left. Both cross sections have not changed significantly since 2012 because of prevailing dry conditions (Table 3).

The surveys of cross sections 3, and 4 show that the original channel (Oxbow) is aggrading (Figs. 7 & 8), especially where it is influenced by backwater from the creek at the downstream end (Fig. 8). Figure 10 shows the cross section locations and the general location of pilot channel bank erosion in the vicinity of cross section 3.






Figure 5: Cross section 1, located upstream from restored reach. Downstream view.




Figure 6: Cross section 2, located at the upper end of the pilot reach. Downstream view.




Figure 7: Cross section 3, located in the middle of the pilot channel. Downstream view.




Figure 8: Cross section 4, located at the downstream end of the pilot channel.  
Downstream view.




Figure 9: Cross section 5, located downstream of restored reach. Downstream view.

Table 3. Cross Section Area (square feet) and Changes from Each Survey

Cross Section Area (ft <sup>2</sup> )					
Survey	XSEC 1	XSEC 2	XSEC 3	XSEC 4	XSEC 5
<i>Pre-restoration</i>	88.7	386.0 <sup>1</sup>	158.4 <sup>1</sup>	290.2 <sup>2</sup>	92.8
<i>2009 Post-restoration</i>	--	377.2 <sup>1</sup>	164.9 <sup>1</sup>	284.5 <sup>2</sup>	--
<i>2010 Year 1</i>	82.3 <sup>1</sup>	383.3 <sup>1</sup>	171.8 <sup>1</sup>	273.5 <sup>2</sup>	95.0
<i>2012 Year 3</i>	91.4	355.8	210.2	262.3	94.9 <sup>3</sup>
<i>2014 Year 5</i>	94.2	377.7	203.9	265.7	95.2
Change in Area (ft <sup>2</sup> and %)					
2009 Post –2009 pre	No change	-8.8	6.4	-6.1	No change
2010– 2009 Pre	-6.8 <sup>1</sup>	-2.0	13.3	-17.1	2.1
2010– 2009 Post	Same as above	6.8	6.9	-11.0	Same as above
2012–2010	9.2 (11%)	-23.5 (7%)	38.4 (22%)	-11.2 (4%)	-0.1 (0%)
2014–2012	2.7 (3%)	21.9 (6%)	-6 (3%)	3.4 (1%)	0.3 (0%)
Cum. change (prerestoration to 2014)	5.5 (6%)	-8.3 (2%)	45.4 (29%)	-24.5 (8%)	2.4 (3%)
Cum. change (postrestoration to 2014)	Same as above	0.5 (0%)	39.0 (24%)	-18.8 (7%)	Same as above

**Notes:** Numbers in red denote sediment aggradation and a loss in cross section area between surveys (an increase in sediment at the transect). Numbers in green denote sediment degradation and an increase in cross section area between surveys (a decrease in sediment at the transect).

<sup>1</sup>Values adjusted slightly from previous reports for technical reasons.

<sup>2</sup>A treefall precluded 2 survey shots near the left benchmark in 2010. Prior cross sectional areas were adjusted by removing those shots for better inter-annual comparison of channel shape.

<sup>3</sup>Value corrected from Smith et al. (2012).




Figure 10: Site sketch map showing cross section locations and general area of bank erosion. Map redrawn from WRA (2010). Pilot channel alignment was originally straight between cross sections 2 and 3.

### 3.2 Riparian Vegetation

As previously reported, both upland and riparian native vegetation appeared to be recovering well, with a very high cover of native plants, a high survival rate of planted trees and shrubs, and very low cover of non-native invasive plants. Both vegetation goals stated for year 5 have been achieved: (1) survival of plantings currently exceed 80 percent, and (2) cover of plants rated as “high” or “moderate” invasive species in the California Invasive Plant Inventory do not exceed 5 percent.

Upland impacted areas were almost completely covered with spreading vines of California blackberry (*Rubus ursinus*), common (stinging) nettle (*Urtica dioica*) and common snowberry (*Symphoricarpos albus*) totaling at least 95% cover. Planted alder trees (*Alnus spp.*) have reached heights of 10 to 20 feet in the restored area and provide good canopy cover over the restored reach. No upland invasive weeds were observed. In contrast to the Year 1 report, black mustard (*Brassica nigra*) and poison



hemlock (*Conium maculatum*) were absent from the upland area, as were French broom (*Genista monspessulana*), and bull thistle (*Cirsium vulgare*) reported in Year 3.

In-stream vegetation was dominated by rooted cuttings of western dogwood (*Cornus sericea* ssp. *occidentalis*). These cuttings were quite extensive along the natural channel and the pilot channel, but were absent from the oxbow. As noted in the Year 1 monitoring reports, in-stream and stream bank herbaceous vegetation was not recovering as well as the upland vegetation, as many of the planted species were likely washed away during the first year. In Year 5, in-stream vegetation was more prevalent, though less so in the pilot channel where in-stream boulder and root structures dominate. While the in-stream vegetation was free of any serious noxious weeds, one potential concern in Year 3 was the extensive spread of the non-native water cress (*Nasturtium officinale*) which covered the entire streambed of the pilot channel. Some native water cress was noted in Year 5 though it did not appear to cover as much area as previously reported; drought conditions resulting in less flow within the channel may be a factor in its spread.

### 3.3 Wildlife

One special status species was observed during the October 22<sup>nd</sup> visit: California coast steelhead. A single juvenile fish was observed in the reference reach upstream of the pilot channel in a large pool. No California red-legged frogs were observed as have been on previous visits. Conditions at the time of the visit were not conducive to observing avian species, however several avian species were heard calling including: chestnut-backed chickadee (*Poecile rufescens*), California quail (*Callipepla californica*), acorn woodpecker (*Melanerpes formicivorus*), western wood peewee (*Contopus sordidulus*), Bewick's wren (*Thryomanes bewickii*), and western scrub jay (*Aphelocoma californica*). Common species, western gray squirrel (*Sciurus griseus*) was also observed.

Habitat features such as backwater refugia, instream woody debris and cover, and slow moving, deep pools were present and similar to previous years observations of these features. Overall, the newly created backwater habitat located at the downstream confluence of the oxbow and pilot channel provide good cover for herpetofauna. Similarly, the pilot channel has developed into a step-pool configuration which provides overall improved habitat complexity for both herpetofauna and fish. Growth and canopy development of trees planted in the restored area offer shading which in turn improves water quality, and root structures that extend into the bank offer cover from predators.

The results of the CDFG California Stream Bioassessment Procedure for Year 5 are provided in Table 4. Individual habitat parameters that contribute to the stream habitat assessment scores are presented in Table 5. Results of water quality parameters for

Year 5 are provided in Table 6. Transect locations correspond with geomorphic cross-section transects; for clearer analysis only three transects (upstream, mid-pilot channel, and downstream) were utilized for comparison. Datasheets for all ten habitat parameters for Year 5 monitoring are provided in Appendix B.

Table 4. CDFG Stream Bioassessment Physical Scores for Monitoring Years

Monitoring Year	XSEC 1 Stream Habitat Score	XSEC 3 Stream Habitat Score	XSEC 5 Stream Habitat Score
Baseline	169	133	164
Year 1	162	129	156
Year 2	162	120	152
Year 3	174	137	168
Year 5	169	146	155

Table 5. Habitat Parameters of the CDFG Stream Bioassessment Scores for Monitoring Years

Habitat Parameter	XSEC 1					XSEC 3					XSEC 5				
	Baseline	Year 1	Year 2	Year 3	Year 5	Baseline	Year 1	Year 2	Year 3	Year 5	Baseline	Year 1	Year 2	Year 3	Year 5
Epifaunal Substrate/Cover	18	18	18	18	20	10	13	14	18	20	16	16	16	16	20
Embeddedness	15	16	12	16	16	13	10	9	16	11	18	16	13	16	13
Velocity/Depth Regimes	16	15	15	18	18	13	15	15	16	16	15	15	12	17	15
Sediment Deposition	10	5	12	15	10	10	6	8	10	8	15	8	12	13	6
Channel Flow Status	16	13	14	13	12	16	11	12	12	10	15	13	12	16	10
Channel Alteration	20	20	18	18	20	18	18	16	10	13	19	19	18	16	20
Frequency of Riffles	18	18	18	18	17	17	19	16	19	17	18	18	17	18	15
Left Bank Stability	10	10	9	9	8	8	5	3	3	9	10	9	9	10	10
Right Bank Stability	9	9	9	9	9	2	3	2	5	5	7	8	9	9	8

<b>Vegetative Protection, Left Bank</b>	10	10	10	10	10	9	5	3	6	10	7	7	9	10	10
<b>Vegetative Protection, Right Bank</b>	8	9	9	10	10	4	5	4	8	9	5	8	8	8	9
<b>Riparian Vegetative Zone Width, Left Bank</b>	10	10	10	10	10	10	10	10	8	10	10	10	10	10	10
<b>Riparian Vegetative Zone Width, Right Bank</b>	9	9	8	10	9	3	9	8	6	8	9	9	7	9	9
<b>Total</b>	<i>169</i>	<i>162</i>	<i>162</i>	<i>174</i>	<i>169</i>	<i>133</i>	<i>129</i>	<i>120</i>	<i>137</i>	<i>146</i>	<i>164</i>	<i>156</i>	<i>152</i>	<i>168</i>	<i>155</i>

Results from the stream habitat assessment conducted in Year 5 indicate the overall physical habitat quality within the pilot channel (XSEC 3) has improved significantly since Year 1. Substantial improvements were noted in Epifaunal Substrate and Available Cover with an increase in parameter conditions from marginal to optimal. Embeddedness and Velocity/Depth Regimes also increased to within the optimal condition category, likely due to the increased complexity of the step pool complex. Vegetative protection increased from marginal to sub-optimal. Additional improved habitat parameters resulting from project activities include Frequency of Riffles (or bends) and Riparian Vegetative Zone Width. While scores in habitat parameters for sediment deposition and channel flow status decreased, these parameters have a tendency to fluctuate based on rainfall and movement of sediment plugs. Characteristically, decreases noted in the pilot channel were also noted both upstream and downstream of XSec 3.

Notably the overall scores decreased slightly in the upstream and downstream reaches in Year 5. These decreases were most evident in those parameters that are variable based on season. Drought conditions over the past several years may have contributed to lower values overall in Potrero Creek, as well as the naturally dynamic nature of the creek. Thus the criteria that all parameters should at least meet suboptimal conditions have not been met; however, this is likely due to environmental factors and not the result of activities within the pilot channel.

The restored reach habitat assessment value is 10 percent greater than the pre-existing value. While this increase is substantially less than the 50 percent increase stated in the performance criteria, it is not without merit. A 50 percent increase would have resulted

in a habitat value of 199, which is substantially higher than the value for the reference reach and may be unobtainable given environmental factors.

The second criterion for the bio-assessment is that all parameters increase to at least suboptimal by Year 5. This was achieved on nearly all parameters, with the exception of the following: sediment deposition, left and right bank stability, left and right bank vegetative protection, and right bank vegetative zone. A 50 percent decrease in sediment deposition value was recorded in the upstream reach in Year 5 suggesting that there was greater deposition throughout the creek in Year 5, not just in the pilot channel, which affects meeting this criterion. Furthermore, the value for vegetative protection, left bank stability, and right bank vegetative zone was the same as the upstream reach suggesting this is a normal condition and that in-stream and bank vegetation throughout Potrero Creek is subject to erosive factors and may never meet suboptimal values anywhere in the reach. The only parameter that failed to show measurable increases was right bank stability, though this value did increase from poor to marginal when compared with baseline conditions.

Table 6. Water Quality Results for Monitoring Years <sup>1</sup>															
Parameter Sampled	XSEC 1					XSEC 3					XSEC 5				
	Baseline	Year 1	Year 2	Year 3	Year 5	Baseline	Year 1	Year 2	Year 3	Year 5	Baseline	Year 1	Year 2	Year 3	Year 5
Water Temperature (Celsius)	14.5	13.4	13.6	6.5	-	-	13.5	13.6	6.3	-	14.0	13.8	13.8	5.9	-
pH	7.5	6.6	7.2	6.5	-	-	6.6	7.1	6.3	-	7.6	6.7	7.3	5.9	-
Conductivity (µs)	-	746	837	887	-	-	747	836	895	-	-	761	776	906	-

Notes: <sup>1</sup>Year three parameters were measured during baseflow conditions on Dec. 12, 2012. Water quality was not measured during Year 5.

While water quality was not measured in Year 5 due to equipment failure in the field, it is anticipated that better shading may contribute to lower water temperatures and thus lower conductivity values now and in the future. Despite the fact that vegetative values remain low, shading and canopy cover has increased since Year 1. Overall, conductivity measurements since monitoring began on the project have not exceeded maximum limits for steelhead, which are more tolerant of water quality changes than other salmonid species. Similarly drought conditions can also affect water quality, making inferences about water quality with relation to the project difficult. Values taken from

the upstream reach were generally similar to the pilot channel, with the lowest values found downstream. This suggests water quality changes may vary based on other factors including upstream inputs, shading, and flow. Thus, the criterion for water quality improvement is not adequate for the purposes of this study, and cannot likely be met.

## 4 Recommendations

Criteria and standards for this project are stated in the “Goals” section of this report. Below we compare the Year 5 monitoring observations to specific Year 5 project goals.

### 4.1 Geomorphology

The Year 5 goal for geomorphology is specific: *“The pilot channel banks will be stabilized and not show signs of significant erosion.”* This condition is being met at cross section 4 and, to a lesser degree, at cross section 2. Although the cross section 2 survey does not indicate lateral erosion (Fig. 6), visual inspection in August 2011, September 2012, and August 2014 indicate that the right bank of cross section 2 is slowly eroding. This bank is the plug that directs flow away from the old channel into the pilot channel. Bank integrity at this location is critical to project success, and is buttressed by large wood and rock.

The right bank erosion problem noted near cross section 2 accelerates downstream from cross section 2 to cross section 3 (Fig. 7), where the problem was considered severe in 2012. The erosion is the direct result of lateral channel migration, forced by the growth of a side-attached bar on the left side. An indirect cause is the lack of an adequate floodplain width in this river reach. The observed channel widening was anticipated since the constructed channel was an undersized “pilot channel” that was left to enlarge and mature through time. The channel will probably continue to widen during high flow events. It is unclear how large the channel will become.

The bank retreated about 5 feet to the right between the 2010 and 2012 surveys. No further bank erosion occurred between 2010 and 2014 because there were no significant flows during that period. The erosion rate will increase again when normal or high flow years occur. If bank erosion does not gradually abate, the pilot channel may eventually reconnect to the original channel.

Annual visual inspection following high runoff years, and appropriate response to high erosion rates will guard against project failure.

## 4.2 Riparian Vegetation

Upland vegetation is recovering well, as demonstrated by a high absolute cover of native species, and little bare ground, no observed invasive plants. No additional upland planting is recommended at this time.

In-stream and bankside vegetation met the 80 percent cover criteria in Year 5 and the banks of the pilot channel appeared relatively stable compared with previous years. Root structures and large boulders provide additional structural complexity where in-stream plants such as *Carex spp.* and *scirpus*, have failed to take hold. Overall, measures implemented in year 3 including trimming and the addition of dogwood poles have increased overall in-stream cover when compared with the reference reach. Based on the meeting of performance criteria, no additional measures are recommended.

## 4.3 Wildlife

On a qualitative level, the pilot channel provides better habitat than what was previously present in the oxbow. Therefore, while the overall habitat assessment value from Year 5 does not meet the performance criteria outlined in the *Potrero Creek Restoration Monitoring and Management Plan*, as required by the Project's RWQCB, CDFG, and Corps, the habitat is measurably better than baseline conditions. A 10 percent increase in value overall from baseline conditions was measured in Year 5 and nearly all values were at least suboptimal or increasing in value. No decreases in values were measured except where such decreases were evident throughout the reach and likely the result of environmental factors rather than project-related. As such, no further wildlife monitoring is recommended.

## 5 References

- Rosenberg, L. 2001. Geologic resources and constraints Monterey County California. County of Monterey Environmental Resource Policy Department.
- Smith DP, Riggs D., Hauser C., and Goodmansen A. (2012) Potrero Creek Restoration, Santa Lucia Preserve, Monterey County (CA): Year Three Monitoring: The Watershed Institute, California State Monterey Bay, Publication No. WI-2012-07, 43pp.
- WRA (2009). Restoration and Monitoring Management Plan, Potrero Creek, Santa Lucia Preserve, Monterey County, California: Report prepared by WRA Consultants for Santa Lucia Community Services District, 23pp + appendices. (This report was presented in 2007, then revised in 2009)

WRA (2010). Potrero Creek restoration project, Santa Lucia Preserve, Monterey County, California: Report prepared by WRA Consultants for Santa Lucia Community Services District, 19pp + appendices.

WRA (2012). Year Two Monitoring Report, Potrero Creek restoration project, Santa Lucia Preserve, Monterey County, California: Prepared by WRA Consultants for Santa Lucia Community Services District, 16pp + appendices.



## 6 Appendix A: Photomonitoring

Photo point P1: Right bank of XSEC 1, downstream view. Arrow points to root wad. Top left is 2009 post-construction. Top right is 2012 year3 monitoring. Bottom is 2014 Year 5 monitoring.





Photo point P2: Left bank of XSEC 2, downstream view. Arrow points to bent tree. Top left is 2009 post-construction. Top right is 2012 year3 monitoring. Bottom is 2014 Year 5 monitoring.





Photo point P3: Left bank of XSEC 3, upstream view. Arrow points to mouth of pilot channel. Top left is 2009 post-construction. Top right is 2012 year 3 monitoring. Bottom is 2014 Year 5 monitoring.





Photo point P4: Left bank of XSEC 4, upstream view. Arrow points to temporary benchmark. Top left is 2009 post-construction. Top right is 2012 year 3 monitoring. Bottom is 2014 Year 5 monitoring.





Photo point P4: Left bank of XSEC 4, downstream view. Arrow points to oxbow confluence. Top left is 2009 post-construction. Top right is 2012 year 3 monitoring. Bottom is 2014 Year 5 monitoring.





Photo point P5: Right bank of XSEC 5, upstream view. Arrow points to overhanging tree. Top left is 2009 post-construction. Top right is 2012 year 3 monitoring. Bottom is 2014 Year 5 monitoring.





Mouth of pilot channel: downstream view. Arrow points to rock and root wad. Top left is 2009 post-construction. Top right is 2012 year 3 monitoring. Bottom is 2014 Year 5 monitoring



## **7 Appendix B: Physical Habitat Quality Assessment Field Notes**



**PHYSICAL HABITAT QUALITY**  
(California Stream Bioassessment Procedure)

WATERSHED/ STREAM: Potrero Creek  
COMPANY/ AGENCY: WPA  
SITE DESCRIPTION: X SEC 1 (UPSTREAM)

DATE/ TIME: 10/22/2014  
SAMPLE ID NUMBER: —

Circle the appropriate score for all 20 habitat parameters. Record the total score on the front page of the CBW.

HABITAT PARAMETER	CONDITION CATEGORY			
	OPTIMAL	SUBOPTIMAL	MARGINAL	POOR
<b>1. Epifaunal Substrate/ Available Cover</b>	Greater than 70% (50% for low gradient streams) of substrate favorable for epifaunal colonization and fish cover; most favorable is a mix of snags, submerged logs, undercut banks, cobble or other stable habitat and at stage to allow full colonization potential (i.e., logs/snags that are not new fall and not transient).	40-70% (30-50% for low gradient streams) mix of stable habitat; well-suited for full colonization potential; adequate habitat for maintenance of populations; presence of additional substrate in the form of newfall, but not yet prepared for colonization (may rate at high end of scale).	20-40% (10-30% for low gradient streams) mix of stable habitat; habitat availability less than desirable; substrate frequently disturbed or removed.	Less than 20% (10% for low gradient streams) stable habitat; lack of habitat is obvious; substrate unstable or lacking.
	(20) 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
<b>2. Embeddedness</b>	Gravel, cobble, and boulder particles are 0-25% surrounded by fine sediment. Layering of cobble provides diversity of niche space.	Gravel, cobble, and boulder particles are 25-50% surrounded by fine sediment.	Gravel, cobble, and boulder particles are 50-75% surrounded by fine sediment.	Gravel, cobble, and boulder particles are more than 75% surrounded by fine sediment.
	20 19 18 17 (16)	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
<b>3. Velocity/ Depth Regimes</b> (deep < 0.5 m, slow < 0.3 m/s)	All four velocity/depth regimes present (slow-deep, slow-shallow, fast-deep, fast-shallow).	Only 3 of the 4 regimes present (if fast-shallow is missing, score lower than if missing other regimes).	Only 2 of the 4 habitat regimes present (if fast-shallow or slow-shallow are missing, score low).	Dominated by 1 velocity/ depth regime (usually slow-deep).
	20 19 (18) 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
<b>4. Sediment Deposition</b>	Little or no enlargement of islands or point bars and less than 5% (<20% for low-gradient streams) of the bottom affected by sediment deposition.	Some new increase in bar formation, mostly from gravel, sand or fine sediment; 5-30% (20-50% for low-gradient) of the bottom affected; slight deposition in pools.	Moderate deposition of new gravel, sand or fine sediment on old and new bars; 30-50% (50-80% for low-gradient) of the bottom affected; sediment deposits at obstructions, constrictions, and bends; moderate deposition of pools prevalent.	Heavy deposits of fine material, increased bar development; more than 50% (80% for low-gradient) of the bottom changing frequently; pools almost absent due to substantial sediment deposition.
	20 19 18 17 16	15 14 13 12 11	(10) 9 8 7 6	5 4 3 2 1 0
<b>5. Channel Flow Status</b>	Water reaches base of both lower banks, and minimal amount of channel substrate is exposed.	Water fills >75% of the available channel; or <25% of channel substrate is exposed.	Water fills 25-75% of the available channel, and/or riffle substrates are mostly exposed.	Very little water in channel and mostly present as standing pools.
	20 19 18 17 16	15 14 13 (12) 11	10 9 8 7 6	5 4 3 2 1 0

Total = 76

Parameters to be evaluated in an area longer than the sampling reach

HABITAT PARAMETER	CONDITION CATEGORY																			
	OPTIMAL					SUBOPTIMAL					MARGINAL					POOR				
6. Channel Alteration	Channelization or dredging absent or minimal; stream with normal pattern.					Some channelization present, usually in areas of bridge abutments; evidence of past channelization, i.e., dredging, (greater than past 20 yr) may be present, but recent channelization is not present.					Channelization may be extensive; embankments or shoring structures present on both banks; and 40 to 80% of stream reach channelized and disrupted.					Banks shored with gabion or cement; over 80% of the stream reach channelized and disrupted. Instream habitat greatly altered or removed entirely.				
	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1
7. Frequency of Riffles (or bends)	Occurrence of riffles relatively frequent; ratio of distance between riffles divided by width of the stream <7:1 (generally 5 to 7); variety of habitat is key. In streams where riffles are continuous, placement of boulders or other large, natural obstruction is important.					Occurrence of riffles infrequent; distance between riffles divided by the width of the stream is between 7 to 15.					Occasional riffle or bend; bottom contours provide some habitat; distance between riffles divided by the width of the stream is between 15 to 25.					Generally all flat water or shallow riffles; poor habitat; distance between riffles divided by the width of the stream is a ratio of >25.				
	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1
8. Bank Stability (score each bank) Note: determine left of right side by facing downstream	Banks stable; evidence of erosion or bank failure absent or minimal; little potential for future problems. <5% of bank affected.					Moderately stable; infrequent, small areas of erosion mostly healed over. 5-30% of bank in reach has areas of erosion.					Moderately unstable; 30-60% of bank in reach has areas of erosion; high erosion potential during floods.					Unstable; many eroded areas; "raw" areas frequent along straight sections and bends; obvious bank sloughing; 60-100% of bank has erosional scars.				
	Left Bank	10	9			8	7	6			5	4	3			2	1	0		
	Right Bank	10	9			8	7	6			5	4	3			2	1	0		
9. Vegetative Protection (score each bank) Note: determine left or right side by facing downstream.	More than 90% of the streambank surfaces and immediate riparian zones covered by native vegetation, including trees, understory shrubs, or nonwoody macrophytes; vegetative disruption through grazing or mowing minimal or not evident; almost all plants allowed to grow naturally.					70-90% of the streambank surfaces covered by native vegetation, but one class of plants is not well-represented; disruption evident but not affecting full plant growth potential to any great extent; more than one-half of the potential plant stubble height remaining.					50-70% of the streambank surfaces covered by vegetation; disruption obvious; patches of bare soil or closely cropped vegetation common; less than one-half of the potential plant stubble height remaining.					Less than 50% of the streambank surfaces covered by vegetation; disruption of streambank vegetation is very high; vegetation has been removed to 5 centimeters or less in average stubble height.				
	Left Bank	10	9			8	7	6			5	4	3			2	1	0		
	Right Bank	10	9			8	7	6			5	4	3			2	1	0		
10. Riparian Vegetative Zone Width (score each bank riparian zone)	Width of riparian zone >18 meters; human activities (i.e., parking lots, roadbeds, clear-cuts, lawns, or crops) have not impacted zone.					Width of riparian zone 12-18 meters; human activities have impacted zone only minimally.					Width of riparian zone 6-12 meters; human activities have impacted zone a great deal.					Width of riparian zone <6 meters; little or no riparian vegetation due to human activities.				
	Left Bank	10	9			8	7	6			5	4	3			2	1	0		
	Right Bank	10	9			8	7	6			5	4	3			2	1	0		

Total score = 169

**PHYSICAL HABITAT QUALITY**  
(California Stream Bioassessment Procedure)

WATERSHED/ STREAM: Potrero Creek  
COMPANY/ AGENCY: WRA  
SITE DESCRIPTION: XSEC 3 (Project Area)

DATE/ TIME: 10/22/14  
SAMPLE ID NUMBER: —

Circle the appropriate score for all 20 habitat parameters. Record the total score on the front page of the CBW.

HABITAT PARAMETER	CONDITION CATEGORY			
	OPTIMAL	SUBOPTIMAL	MARGINAL	POOR
<b>1. Epifaunal Substrate/ Available Cover</b>  Greater than 70% (50% for low gradient streams) of substrate favorable for epifaunal colonization and fish cover; most favorable is a mix of snags, submerged logs, undercut banks, cobble or other stable habitat and at stage to allow full colonization potential (i.e., logs/snags that are <u>not</u> new fall and <u>not</u> transient).	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
<b>2. Embeddedness</b>  Gravel, cobble, and boulder particles are 0-25% surrounded by fine sediment. Layering of cobble provides diversity of niche space.	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
<b>3. Velocity/ Depth Regimes</b>  (deep < 0.5 m, slow < 0.3 m/s)	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
<b>4. Sediment Deposition</b>  Little or no enlargement of islands or point bars and less than 5% (<20% for low-gradient streams) of the bottom affected by sediment deposition.	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
<b>5. Channel Flow Status</b>  Water reaches base of both lower banks, and minimal amount of channel substrate is exposed.	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0

Total p1 = 65

Parameters to be evaluated in an area longer than the sampling reach

HABITAT PARAMETER	CONDITION CATEGORY																							
	OPTIMAL					SUBOPTIMAL					MARGINAL					POOR								
<b>6. Channel Alteration</b>	Channelization or dredging absent or minimal; stream with normal pattern.					Some channelization present, usually in areas of bridge abutments; evidence of past channelization, i.e., dredging, (greater than past 20 yr) may be present, but recent channelization is not present.					Channelization may be extensive; embankments or shoring structures present on both banks; and 40 to 80% of stream reach channelized and disrupted.					Banks shored with gabion or cement; over 80% of the stream reach channelized and disrupted. Instream habitat greatly altered or removed entirely.								
	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0			
<b>7. Frequency of Riffles (or bends)</b>	Occurrence of riffles relatively frequent; ratio of distance between riffles divided by width of the stream <7:1 (generally 5 to 7); variety of habitat is key. In streams where riffles are continuous, placement of boulders or other large, natural obstruction is important.					Occurrence of riffles infrequent; distance between riffles divided by the width of the stream is between 7 to 15.					Occasional riffle or bend; bottom contours provide some habitat; distance between riffles divided by the width of the stream is between 15 to 25.					Generally all flat water or shallow riffles; poor habitat; distance between riffles divided by the width of the stream is a ratio of >25.								
	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0			
<b>8. Bank Stability</b> (score each bank) Note: determine left of right side by facing downstream	Banks stable; evidence of erosion or bank failure absent or minimal; little potential for future problems. <5% of bank affected.					Moderately stable; infrequent, small areas of erosion mostly healed over. 5-30% of bank in reach has areas of erosion.					Moderately unstable; 30-60% of bank in reach has areas of erosion; high erosion potential during floods.					Unstable; many eroded areas; "raw" areas frequent along straight sections and bends; obvious bank sloughing; 60-100% of bank has erosional scars.								
	Left Bank	10	9	8	7	6	5	4	3	2	1	0	Left Bank	10	9	8	7	6	5	4	3	2	1	0
	Right Bank	10	9	8	7	6	5	4	3	2	1	0	Right Bank	10	9	8	7	6	5	4	3	2	1	0
<b>9. Vegetative Protection</b> (score each bank) Note: determine left or right side by facing downstream.	More than 90% of the streambank surfaces and immediate riparian zones covered by native vegetation, including trees, understory shrubs, or nonwoody macrophytes; vegetative disruption through grazing or mowing minimal or not evident; almost all plants allowed to grow naturally.					70-90% of the streambank surfaces covered by native vegetation, but one class of plants is not well-represented; disruption evident but not affecting full plant growth potential to any great extent; more than one-half of the potential plant stubble height remaining.					50-70% of the streambank surfaces covered by vegetation; disruption obvious; patches of bare soil or closely cropped vegetation common; less than one-half of the potential plant stubble height remaining.					Less than 50% of the streambank surfaces covered by vegetation; disruption of streambank vegetation is very high; vegetation has been removed to 5 centimeters or less in average stubble height.								
	Left Bank	10	9	8	7	6	5	4	3	2	1	0	Left Bank	10	9	8	7	6	5	4	3	2	1	0
	Right Bank	10	9	8	7	6	5	4	3	2	1	0	Right Bank	10	9	8	7	6	5	4	3	2	1	0
<b>10. Riparian Vegetative Zone Width</b> (score each bank riparian zone)	Width of riparian zone >18 meters; human activities (i.e., parking lots, roadbeds, clear-cuts, lawns, or crops) have not impacted zone.					Width of riparian zone 12-18 meters; human activities have impacted zone only minimally.					Width of riparian zone 6-12 meters; human activities have impacted zone a great deal.					Width of riparian zone <6 meters; little or no riparian vegetation due to human activities.								
	Left Bank	10	9	8	7	6	5	4	3	2	1	0	Left Bank	10	9	8	7	6	5	4	3	2	1	0
	Right Bank	10	9	8	7	6	5	4	3	2	1	0	Right Bank	10	9	8	7	6	5	4	3	2	1	0

Total pitz = 146

**PHYSICAL HABITAT QUALITY**  
(California Stream Bioassessment Procedure)

WATERSHED/ STREAM: Potrero Creek

DATE/ TIME: 10/22/14

COMPANY/ AGENCY: WRA

SAMPLE ID NUMBER:                     

SITE DESCRIPTION: X SEC 5 (Downstream)

Circle the appropriate score for all 20 habitat parameters. Record the total score on the front page of the CBW.

HABITAT PARAMETER	CONDITION CATEGORY			
	OPTIMAL	SUBOPTIMAL	MARGINAL	POOR
<b>1. Epifaunal Substrate/ Available Cover</b>	Greater than 70% (50% for low gradient streams) of substrate favorable for epifaunal colonization and fish cover; most favorable is a mix of snags, submerged logs, undercut banks, cobble or other stable habitat and at stage to allow full colonization potential (i.e., logs/snags that are <u>not</u> new fall and <u>not</u> transient).	40-70% (30-50% for low gradient streams) mix of stable habitat; well-suited for full colonization potential; adequate habitat for maintenance of populations; presence of additional substrate in the form of newfall, but not yet prepared for colonization (may rate at high end of scale).	20-40% (10-30% for low gradient streams) mix of stable habitat; habitat availability less than desirable; substrate frequently disturbed or removed.	Less than 20% (10% for low gradient streams) stable habitat; lack of habitat is obvious; substrate unstable or lacking.
	(20) 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
<b>2. Embeddedness</b>	Gravel, cobble, and boulder particles are 0-25% surrounded by fine sediment. Layering of cobble provides diversity of niche space.	Gravel, cobble, and boulder particles are 25-50% surrounded by fine sediment.	Gravel, cobble, and boulder particles are 50-75% surrounded by fine sediment.	Gravel, cobble, and boulder particles are more than 75% surrounded by fine sediment.
	20 19 18 17 16	15 14 (13) 12 11	10 9 8 7 6	5 4 3 2 1 0
<b>3. Velocity/ Depth Regimes</b> (deep<0.5 m, slow<0.3 m/s)	All four velocity/depth regimes present (slow-deep, slow-shallow, fast-deep, fast-shallow).	Only 3 of the 4 regimes present (if fast-shallow is missing, score lower than if missing other regimes).	Only 2 of the 4 habitat regimes present (if fast-shallow or slow-shallow are missing, score low).	Dominated by 1 velocity/ depth regime (usually slow-deep).
	20 19 18 17 16	(15) 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
<b>4. Sediment Deposition</b>	Little or no enlargement of islands or point bars and less than 5% (<20% for low-gradient streams) of the bottom affected by sediment deposition.	Some new increase in bar formation, mostly from gravel, sand or fine sediment; 5-30% (20-50% for low-gradient) of the bottom affected; slight deposition in pools.	Moderate deposition of new gravel, sand or fine sediment on old and new bars; 30-50% (50-80% for low-gradient) of the bottom affected; sediment deposits at obstructions, constrictions, and bends; moderate deposition of pools prevalent.	Heavy deposits of fine material, increased bar development; more than 50% (80% for low-gradient) of the bottom changing frequently; pools almost absent due to substantial sediment deposition.
	20 19 18 17 16	15 14 13 12 11	10 9 8 7 (6)	5 4 3 2 1 0
<b>5. Channel Flow Status</b>	Water reaches base of both lower banks, and minimal amount of channel substrate is exposed.	Water fills >75% of the available channel; or <25% of channel substrate is exposed.	Water fills 25-75% of the available channel, and/or riffle substrates are mostly exposed.	Very little water in channel and mostly present as standing pools.
	20 19 18 17 16	15 14 13 12 11	(10) 9 8 7 6	5 4 3 2 1 0

Total PI = 64

Parameters to be evaluated in an area longer than the sampling reach

HABITAT PARAMETER	CONDITION CATEGORY																				
	OPTIMAL					SUBOPTIMAL					MARGINAL					POOR					
<b>6. Channel Alteration</b>	Channelization or dredging absent or minimal; stream with normal pattern.					Some channelization present, usually in areas of bridge abutments; evidence of past channelization, i.e., dredging, (greater than past 20 yr) may be present, but recent channelization is not present.					Channelization may be extensive; embankments or shoring structures present on both banks; and 40 to 80% of stream reach channelized and disrupted.					Banks shored with gabion or cement; over 80% of the stream reach channelized and disrupted. Instream habitat greatly altered or removed entirely.					
	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
<b>7. Frequency of Riffles (or bends)</b>	Occurrence of riffles relatively frequent; ratio of distance between riffles divided by width of the stream <7:1 (generally 5 to 7); variety of habitat is key. In streams where riffles are continuous, placement of boulders or other large, natural obstruction is important.					Occurrence of riffles infrequent; distance between riffles divided by the width of the stream is between 7 to 15.					Occasional riffle or bend; bottom contours provide some habitat; distance between riffles divided by the width of the stream is between 15 to 25.					Generally all flat water or shallow riffles; poor habitat; distance between riffles divided by the width of the stream is a ratio of >25.					
	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0
<b>8. Bank Stability</b> (score each bank) Note: determine left of right side by facing downstream	Banks stable; evidence of erosion or bank failure absent or minimal; little potential for future problems. <5% of bank affected.					Moderately stable; infrequent, small areas of erosion mostly healed over. 5-30% of bank in reach has areas of erosion.					Moderately unstable; 30-60% of bank in reach has areas of erosion; high erosion potential during floods.					Unstable; many eroded areas; "raw" areas frequent along straight sections and bends; obvious bank sloughing; 60-100% of bank has erosional scars.					
	Left Bank		10	9		8	7	6			5	4	3			2	1	0			
	Right Bank		10	9		8	7	6			5	4	3			2	1	0			
<b>9. Vegetative Protection</b> (score each bank) Note: determine left or right side by facing downstream.	More than 90% of the streambank surfaces and immediate riparian zones covered by native vegetation, including trees, understory shrubs, or nonwoody macrophytes; vegetative disruption through grazing or mowing minimal or not evident; almost all plants allowed to grow naturally.					70-90% of the streambank surfaces covered by native vegetation, but one class of plants is not well-represented; disruption evident but not affecting full plant growth potential to any great extent; more than one-half of the potential plant stubble height remaining.					50-70% of the streambank surfaces covered by vegetation; disruption obvious; patches of bare soil or closely cropped vegetation common; less than one-half of the potential plant stubble height remaining.					Less than 50% of the streambank surfaces covered by vegetation; disruption of streambank vegetation is very high; vegetation has been removed to 5 centimeters or less in average stubble height.					
	Left Bank		10	9		8	7	6			5	4	3			2	1	0			
	Right Bank		10	9		8	7	6			5	4	3			2	1	0			
<b>10. Riparian Vegetative Zone Width</b> (score each bank riparian zone)	Width of riparian zone >18 meters; human activities (i.e., parking lots, roadbeds, clear-cuts, lawns, or crops) have not impacted zone.					Width of riparian zone 12-18 meters; human activities have impacted zone only minimally.					Width of riparian zone 6-12 meters; human activities have impacted zone a great deal.					Width of riparian zone <6 meters; little or no riparian vegetation due to human activities.					
	Left Bank		10	9		8	7	6			5	4	3			2	1	0			
	Right Bank		10	9		8	7	6			5	4	3			2	1	0			

Total P182 = 155